



Ohm's Law



Wattage varies directly as ratio of voltages squared

$$W_2 = W_1 \times \left(\frac{E_2}{E_1}\right)^2$$

3 Phase Amperes = $\frac{\text{Total Watts}}{\text{Volts X 1.732}}$